

Quillayute River Timber Breakwater Repairs

John Pell

Project Manager

Seattle District

23 June 2016




Quillayute Boat Basin




BUILDING STRONG®

Quillayute Breakwater Repair

- Work scheduled for summer/fall 2016
- Replace missing horizontal boards on Breakwater (15,000 LF)
- Replace missing fasteners(nuts and bolts) on existing boards (150 est.)
 - Significant increase in shoaling in the marina due to sediment breakthrough
- Work will be in the dry during low tides as necessary
- Environmental Compliance
 - NEPA categorical exclusion
 - No Effect MFR for consideration of ESA-listed species



Quillayute Timber Breakwater Repairs



BUILDING STRONG®